

**STATE OF NEW HAMPSHIRE
DEPARTMENT OF TRANSPORTATION**

**MUNICIPALLY-OWNED RED LIST BRIDGES
(Includes RR, Private and Village District Bridges)**

*Municipally-owned bridges requiring interim inspections
due to poor conditions.
These structures are inspected yearly.*

Prepared by the Bridge Management Committee

Approved:

Victoria F. Sheehan, Commissioner

Date

*Effective December 31, 2020
March 11, 2021*

INDEX

2020 Municipal Red List Title Page	1
Index	2
2020 Municipally-Owned Red List Progress Chart	3
Bridges Removed from the Municipal Red List in 2020 through Rehab & Reconstruction	4
Municipal Bridges Added to Red List in 2020 by Inspection	5
Municipal Red List Bridge Summary Key	6
NH Bridge Type Key	8
2020 Municipal Red List Summary by Town or City	9

2020 Municipally-Owned Red List Progress Chart

Year	Year Start Total	Number Added	Number Removed	Year End Total
2004	397	5	29	373
2005	373	2	10	364
2006	364	33	34	363
2007	363	34	27	370
2008	370	21	33	358
2009	358	30	22	366
2010	366	25	32	359
2011	359	27	33	353
2012	353	26	27	352
2013	352	15	23	351
2014	351	20	27	344
2015	344	27	33	338
2016	338	15	29	324
2017	324/253*	16	17	252
2018	252	7	18	241
2019	241	15	13	243
2020	243	7	27	223
2021	223			

* 71 bridges were removed from the 2017 Municipal Red List to comply with the amendment (known as Senate Bill 38) made to *RSA 234:25-a Red List Bridges*.

2020 Breakdown of Red List Bridge Ownership as presently defined

<u>Owner</u>	<u>Red List Bridge Count</u>
Municipality	219
County	0
Private	1
Railroad	2
Village District	1
2020 Year-End Total	<u>223</u>

Bridges Removed from the Municipal Red List in 2020
through Rehab & Reconstruction

<i>Bridge ID</i>	<i>Owner</i>	<i>Facility over Feature</i>	<i>Deck Area</i>	<i>Funded by</i>
1 Alexandria 178/141	Municipality	Bailey Road over Bog Brook	1,195 SF	Town Funds
2 Barrington 139/116	Municipality	Mallego Road over Mallego Brook	216 SF	SAB
3 Bradford 098/117	Municipality	West Meadow Road over Hoyt Brook	485 SF	Town Funds
4 Dummer 042/043	Municipality	Old NH 110 over Upper Ammonoosuc River	1,701 SF	SAB
5 Frankestown 114/062	Municipality	Russell Station Road over Rand Brook	566 SF	Town Funds
6 Frankestown 149/058	Municipality	So New Boston Road over S Br Piscataquog River	1,173 SF	SAB
7 Franconia 055/101	Municipality	Bickford Hill Road over Ham Branch	1,006 SF	Town Funds
8 Gilford 106/099	Municipality	Old Lake Shore Road over Gunstock River	765 SF	SAB
9 Goffstown 136/106	Municipality	Henry Bridge Road over Piscataquog River	4,095 SF	Town Funds
10 Hill 140/099	Municipality	Bunker Hill Road over Needle Shop Brook	608 SF	SAB
11 Hopkinton 178/039	Municipality	Stickney Hill Road over Boutwell Mill Brook	200 SF	Town Funds
12 Keene 140/077	Municipality	Roxbury Street over Beaver Brook	950 SF	SAB
13 Lebanon 154/113	Municipality	Riverside Drive over Mascoma River	1,125 SF	Town Funds
14 Lyme 041/074	Municipality	River Road over Hewes Brook	496 SF	Town Funds
15 Merrimack 113/159	Municipality	Bedford Road over Baboosic Brook	546 SF	SAB
16 Milford 102/165	Municipality	Hartshorn Road over Hartshorn Brook	234 SF	SAB
17 New London 132/067	Municipality	Brookside Drive over Lion Brook	524 SF	Town Funds
18 Portsmouth 240/132	Municipality	Kearsarge Way over PAR	6,156 SF	Town Funds
19 Rochester 114/046	Municipality	Four Rod Road over Rickers Brook	253 SF	Town Funds
20 Salem 116/116	Municipality	Bluff Street Ext over Widow Harris Brook	577 SF	SAB
21 Sandwich 157/101	Municipality	Basket Street over Bearcamp River	434 SF	Town Funds
22 Swanzey 120/072	Municipality	Rabbit Hollow Road over Perry Brook	288 SF	SAB
23 Tamworth 110/072	Municipality	Bunker Hill Road over Mill Brook	544 SF	Town Funds
24 Washington 186/126	Municipality	Ayers Pond Road over Woodward Brook	272 SF	Town Funds
25 Whitefield 159/098	Municipality	Hazen Road over Johns River	215 SF	Town Funds
26 Wilmot 081/066	Municipality	Piper Pond Road over Brook	445 SF	Town Funds
27 Wolfeboro 116/072	Municipality	Pleasant Valley Road over Heath Brook	440 SF	SAB

Bridges Removed: 27

25,507 SF

State Aid Bridge (SAB) Funds: 11 Red List Removals

Town Funds (no State or Federal funds): 16 Red List Removals

Bridges Added to the Municipal Red List in 2020 by Inspection

<i>Bridge ID</i>	<i>Owner</i>	<i>Facility over Feature</i>	<i>Deck Area</i>
1 Bartlett 112/098	Municipality	Foster Street over Brook	228 SF
2 Francestown 119/059	Municipality	Cressy Hill Road over Rand Brook	468 SF
3 Hancock 100/046	Municipality	Windy Row Road over McDowell Reservoir	4,657 SF
4 Hillsborough 061/139	Municipality	Cooledge Road over Beards Brook	653 SF
5 Landaff 119/118	Municipality	Gale Chandler Road over Mill Brook	165 SF
6 Lisbon 063/078	Municipality	School Street over Ammonoosuc River	8,037 SF
7 Winchester 063/101	Municipality	Recycle Way over Ashuelot River	2,310 SF

Total Bridges Added: 7

16,519 SF

Municipal Red List Bridge Summary Key

The Bridge Municipal Red List is comprised of municipally-owned bridges requiring interim inspections due to poor condition. These municipal bridges are inspected once per year.

Definitions of the column headings used in the Bridge Municipal Red List are listed below:

1. Town / City – The Town or City where a bridge is located. If the bridge spans between two Cities or Towns, both are listed.
2. Bridge Number – The six digit bridge number assigned by the Bureau of Bridge Design to identify each structure uniquely within each Town or City.
3. Facility Carried – This is the roadway or rail line carried by the bridge.
4. Facility Crossed – This is the roadway, waterbody, or rail line crossed by the bridge.
5. Est. ADT (Year) – Approximated Average Daily Traffic with the year for which the traffic was estimated.
6. Condition of Deck, Superstructure, Substructure, or Culvert – In accordance with the National Bridge Inspection Standards (NBIS), each major structural element (deck, superstructure, or substructure; or culvert) of a bridge is rated according to its condition. In addition, AASHTO has developed recommended color ratings for bridges to indicate their overall general condition.

“9 = Excellent”	(Green)
“8 = Very Good”	(Green)
“7 = Good”	(Green)
“6 = Satisfactory”	(Yellow)
“5 = Fair”	(Yellow)
“4 = Poor”	(Red)
“3 = Serious”	(Red)
“2 = Failing”	(Red)
“1 = Closed/Failing”	(Red)
“0 = Closed”	(Red)

Note: When a bridge has one or more major structural elements with a condition rating of “4 = Poor” or less, it is considered to be structurally deficient and is added to the Red List.

7. Total Length (ft); Total Width (ft); No. of Spans – Bridge specific information about width and length of bridge to compute deck area.
8. Gross Deck Area (sf) – Multiplication of bridge length times bridge width to develop a bridge deck area. Culverts use the approach roadway width for this calculation as the width of the structure is coded as “zero” within the NBI data.

9. Date of Most Recent Inspection – Actual date that the last field inspection was completed.
10. Bridge Posting – Current bridge posting if required.
11. Structure Type – Using NH Bridge Type abbreviations, the type of bridge structure is noted.
12. Year Modified / Year Built – The year of the most recent major rehabilitation effort and the original year of construction.

NH Bridge Type Key

<u>Abbreviation</u>	<u>Long Description</u>	<u>Abbreviation</u>	<u>Long Description</u>
BAIB	Bailey or similar bridge	SA	Steel Arc
BAS	Bascule Span	SRF	Steel Rigid Frame
BGB	Beam Girder Bridge	SWING	Swing Bridge
CA	Concrete Arch	TB	Timber Bridge
CACUL	Concrete Arch Culvert	TB-C	Covered Bridge
CAR	Concrete Arch Rib	TB-CS	Timber Bridge Conc. Slab
CB	Concrete Box	TPG	Thru Plate Girder
CB-P	Concrete Box-Precast	TS	Timber Slab
CP	Concrete Pipe	TS-P	Prestressed Timber Slab
CRF	Concrete Rigid Frame		
CRF-P	Concrete Rigid Frame-Precast		
CS	Concrete Slab		
CPP	Corrugated Polymer Pipe		
CTB	Concrete Tee Beam		
CTC	Concrete Timber Composite		
DPG	Deck Plate Girder		
DT	Deck Truss		
HT	High Truss		
IB	I Beams without deck		
IB-BP	I Beams w/ Bridge Plank		
IB-C	I Beams w/ Concrete Deck		
IB-G	I Beams w/ Steel Grid		
IB-S	I Beams w/ Steel Plate		
IB-W	I Beams w/ Wood Deck		
INVER	Inverset I-Beam/Concrete		
Jack	Jack Arch Concrete on I-Beams		
LIFT	Vertical Lift		
LT	Low Truss		
MA	Masonry Arch		
MA-CA	Masonry and Conc. Arch		
MP	Metal Pipe		
MP-A	Metal Plate Arch		
MP-B	Metal Plate Box Culvert		
MS	Masonry Slab		
NEBT	Prestressed Bulb Tee		
NEXT	Prestressed NEXT Beams		
PBB	Prestressed Butted Boxes		
PIB	Prestressed I-Beams		
PSB	Prestressed Spread Boxes		
PSC	Prestressed Concrete		
PSS	Prestressed Solid Slabs		
PTB	Prestressed Tee Beams		
PVS	Prestressed Voided Slabs		

2020 MUNICIPAL BRIDGE RED LIST

Town / City	Bridge Number	Facility Carried	Feature Crossed	Est. ADT (Year)	Condition of Deck, Superstructure, Substructure, or Culvert	Total Length (ft); Total Width (ft); No. of Spans	Gross Deck Area (sf)	Date of Most Recent Inspection	Bridge Posting	Structure Type	Year Modified / Year Built
Acworth	105/035	FOREST ROAD	GREAT BROOK	91-19	Culvert 1 Closed - Failing	L=18.0 W=20.0 1-span	360	8/6/2020	E-2	MP	1977
Albany	213/094	DRAKE HILL ROAD	MEADOW BROOK	121-19	Deck 5 Fair Superstructure 5 Fair Substructure 4 Poor	L=24.0 W=26.3 1-span	632	10/21/2020	E-2	CS	1930
Alexandria	096/112	SHEM VALLEY ROAD	BROCK BROOK	88-18	Deck 6 Satisfactory Superstructure 4 Poor Substructure 5 Fair	L=20.0 W=17.0 1-span	340	11/18/2020	E-2	IB-W	1930
Alexandria	136/131	COLE HILL ROAD	FOWLER RIVER	88-18	Deck 6 Satisfactory Superstructure 6 Satisfactory Substructure 4 Poor	L=43.0 W=11.9 1-span	512	11/18/2020	E-2	IB-W	1930
Alstead	058/132	DREWSVILLE ROAD	DARBY BROOK	298-19	Culvert 4 Poor	L=16.0 W=20.0 1-span	320	8/26/2020	E-2	MP	1979
Alstead	058/136	HILL ROAD	DARBY BROOK	91-19	Culvert 2 Critical	L=19.3 W=21.0 1-span	405	8/26/2020	E-2	MP	1974
Alstead	059/134	HILL ROAD	DARBY BROOK	91-19	Deck 5 Fair Superstructure 5 Fair Substructure 4 Poor	L=30.0 W=24.1 1-span	723	8/26/2020	E-2	IB-BP	1970
Alton	141/222	LOON COVE ROAD	WATSON BROOK	91-19	Culvert 4 Poor	L=11.0 W=18.0 1-span	198	12/4/2020	NPR	MP	1968
Amherst	112/071	MONT VERNON ROAD	CEASARS BROOK	199-19	Culvert 4 Poor	L=14.0 W=22.0 2-span	308	10/29/2020	NPR	MP	1956
Amherst	145/106	THORNTONS FERRY RD	BEAVER BROOK	408-19	Culvert 4 Poor	L=20.0 W=20.0 2-span	400	10/29/2020	E-2	MP	1970
Andover	083/098	BRIDGE ROAD	BLACKWATER RIVER	91-19	Deck 6 Satisfactory Superstructure 4 Poor Substructure 7 Good	L=65.0 W=19.0 1-span	1,235	10/14/2020	E-2	TB-C	1882
Andover	104/078	HALL ROAD	BRADLEY BROOK	16-18	Deck 3 Serious Superstructure 5 Fair Substructure 5 Fair	L=16.0 W=18.9 1-span	302	10/12/2020	10 Tons	IB-C	1970/1932
Andover	125/129	ELBOW POND ROAD	MOUNTAIN BROOK	91-19	Deck 5 Fair Superstructure 5 Fair Substructure 3 Serious	L=20.0 W=18.7 1-span	374	10/12/2020	6 Tons	IB-C	1964
Andover	216/139	LAST STREET	SUCKER BROOK	91-19	Deck 9 Excellent Superstructure 9 Excellent Substructure 4 Poor	L=26.5 W=19.5 1-span	517	10/2/2020	E-2	TB	2019/1936
Antrim	113/143	LIBERTY FARM ROAD	NORTH BRANCH RIVER	91-19	Deck 4 Poor Superstructure 4 Poor Substructure 4 Poor	L=32.0 W=16.0 2-span	512	6/26/2020	E-2	PVS	1991
Antrim	174/070	HIGH STREET	GREAT BROOK	248-19	Culvert 4 Poor	L=18.0 W=26.0 1-span	468	6/23/2020	NPR	MP-A	1960

2020 MUNICIPAL BRIDGE RED LIST

Town / City	Bridge Number	Facility Carried	Feature Crossed	Est. ADT (Year)	Condition of Deck, Superstructure, Substructure, or Culvert	Total Length (ft); Total Width (ft); No. of Spans	Gross Deck Area (sf)	Date of Most Recent Inspection	Bridge Posting	Structure Type	Year Modified / Year Built
Auburn	095/127	GRIFFIN MILL ROAD	MAPLE FALLS BROOK	199-19	Deck 1 Closed - Failing Superstructure 1 Closed - Failing Substructure 1 Closed - Failing	L=29.0 W=14.3 1-span	415	7/10/2020	BRC	IB-W	1991/1850
Barnstead	128/056	GRAY ROAD	CROOKED RUN BROOK	179-19	Culvert 4 Poor	L=12.0 W=18.0 1-span	216	9/18/2020	NPR	MP	1970
Bartlett	112/098	FOSTER STREET	BROOK	116-19	Culvert 4 Poor	L=12.0 W=19.0 1-span	228	10/21/2020	6 Tons	MP	1974
Bath	130/162	TOWN ROAD	PETTYBORO BROOK	5-08	Deck 7 Good Superstructure 5 Fair Substructure 4 Poor	L=24.0 W=16.3 1-span	390	11/25/2020	4 Tons	IB-W	1930
Bedford	105/055	BEALS ROAD	BABOOSIC BROOK	510-19	Deck 7 Good Superstructure 7 Good Substructure 4 Poor	L=23.0 W=23.0 1-span	529	7/13/2020	E-2	CS	1984/1928
Belmont	078/132	UNION ROAD	DURGIN BROOK	2,085-19	Deck 4 Poor Superstructure 4 Poor Substructure 6 Satisfactory	L=19.0 W=33.3 1-span	633	8/20/2020	E-2	CTB	1960
Bennington	095/093	ANTRIM ROAD	MONADNOCK MILL CANAL	2,515-19	Deck 4 Poor Superstructure 4 Poor Substructure 6 Satisfactory	L=28.0 W=32.0 1-span	896	10/28/2020	E-2	CTB	1922
Berlin	238/055	MASON STREET	CANAL	5,111-19	Deck 6 Satisfactory Superstructure 7 Good Substructure 4 Poor	L=121.0 W=37.1 2-span	4,494	10/28/2020	E-2	IB-C	1977/1967
Bow	065/140	PAGE ROAD	BELA BROOK	1,187-19	Culvert 3 Serious	L=12.0 W=23.0 1-span	276	6/11/2020	E-2	MP	1950
Bow	182/113	DUNKLEE ROAD	BOW BOG BROOK	2,398-19	Culvert 4 Poor	L=22.0 W=24.0 1-span	528	6/11/2020	NPR	CRF-P	2006
Bradford	104/141	JOHNSON HILL ROAD	WEST BRANCH BROOK	88-18	Deck 2 Critical Superstructure 5 Fair Substructure 5 Fair	L=27.0 W=12.1 1-span	327	12/10/2020	12 Tons	IB-BP	1950
Bradford	140/144	BRADFORD CENTER RD	W BR WARNER RIVER	88-18	Deck 4 Poor Superstructure 5 Fair Substructure 5 Fair	L=61.0 W=18.5 1-span	1,129	12/8/2020	3 Tons	TB-C	1964/1854
Bradford	168/162	BLAISDELL LAKE RD	STREAM	88-18	Deck 5 Fair Superstructure 6 Satisfactory Substructure 3 Serious	L=20.0 W=12.2 1-span	244	12/10/2020	15 Tons	IB-BP	1950
Brentwood	060/054	MILL ROAD	EXETER RIVER	460-19	Culvert 3 Serious	L=30.7 W=18.0 1-span	553	10/27/2020	E-2	MP-A	1967
Bridgewater	156/172	RIVER ROAD	CLAY BROOK	91-19	Culvert 4 Poor	L=21.0 W=21.0 2-span	441	12/1/2020	E-2	CACUL	1960/1900
Bridgewater	166/093	HAMMOND HILL ROAD	WOODMAN BROOK	91-19	Deck 7 Good Superstructure 7 Good Substructure 4 Poor	L=17.0 W=25.0 1-span	425	12/1/2020	E-2	CS	1975

2020 MUNICIPAL BRIDGE RED LIST

Town / City	Bridge Number	Facility Carried	Feature Crossed	Est. ADT (Year)	Condition of Deck, Superstructure, Substructure, or Culvert	Total Length (ft); Total Width (ft); No. of Spans	Gross Deck Area (sf)	Date of Most Recent Inspection	Bridge Posting	Structure Type	Year Modified / Year Built
Bristol	123/079	DANFORTH BROOK RD	DANFORTH BROOK	128-19	Culvert 4 Poor	L=17.0 W=21.0 1-span	357	12/1/2020	E-2	MP	1960
Brookfield	096/070	MOUNTAIN ROAD	HANSON BROOK	233-19	Deck 5 Fair Superstructure 5 Fair Substructure 3 Serious	L=22.0 W=23.0 1-span	506	8/24/2020	E-2	CS	1920
Brookline	065/085	DUPAW GOULD ROAD	LANCY BROOK	561-19	Culvert 4 Poor	L=22.0 W=24.0 1-span	528	11/17/2020	NPR	MP-B	1987
Campton	170/075	PERCH POND ROAD	RYAN BROOK	91-19	Deck 5 Fair Superstructure 5 Fair Substructure 4 Poor	L=26.0 W=25.0 1-span	650	10/2/2020	E-2	CS	1940
Canaan	147/055	POTATO ROAD	INDIAN RIVER	504-19	Deck 5 Fair Superstructure 4 Poor Substructure 7 Good	L=54.0 W=22.1 1-span	1,193	9/1/2020	15 Tons	IB-W	1994/1930
Canaan	172/070	GRIST MILL HILL RD	INDIAN RIVER	373-19	Deck 3 Serious Superstructure 5 Fair Substructure 5 Fair	L=51.0 W=21.0 1-span	1,071	9/14/2020	E-2	IB-C	1956
Candia	151/123	OLD DEERFIELD ROAD	BROOK	146-19	Deck 4 Poor Superstructure 4 Poor Substructure 5 Fair	L=24.0 W=21.3 2-span	511	10/29/2020	5 Tons	MS	1920
Candia	188/105	BEANE ISLAND ROAD	BEAN BROOK	5-19	Deck 5 Fair Superstructure 5 Fair Substructure 4 Poor	L=13.0 W=22.5 1-span	292	10/29/2020	E-2	IB-C	1930
Canterbury	111/101	CLOUGH TAVERN ROAD	FOREST POND BROOK	91-19	Deck 5 Fair Superstructure 5 Fair Substructure 4 Poor	L=19.0 W=20.0 1-span	380	8/19/2020	NPR	IB-G	1990/1940
Charlestown	152/053	BRIDGE STREET	NECRR	779-19	Deck 5 Fair Superstructure 4 Poor Substructure 4 Poor	L=72.0 W=19.8 3-span	1,428	11/16/2020	10 Tons	IB-W	1992
Charlestown	248/060	OLD CHESHIRE TPK	HACKETT BROOK	91-19	Culvert 4 Poor	L=10.0 W=15.0 1-span	150	11/16/2020	NPR	MP	1940
Chester	169/122	SHEPARD HOME ROAD	EXETER RIVER	473-19	Culvert 4 Poor	L=28.0 W=22.0 2-span	616	11/10/2020	NPR	MP	2007/1986
Chester	170/135	HANSON ROAD	EXETER RIVER	1,824-19	Deck 4 Poor Superstructure 5 Fair Substructure 5 Fair	L=31.0 W=28.0 1-span	868	11/10/2020	E-2	IB-C	1932
Claremont	091/118	PLAINS ROAD	SUGAR RIVER	1,455-19	Deck 4 Poor Superstructure 6 Satisfactory Substructure 7 Good	L=194.0 W=36.4 2-span	7,065	12/9/2020	E-2	IB-C	1974
Colebrook	167/120	BEAR ROCK ROAD	W BR MOHAWK RIVER	72-19	Culvert 3 Serious	L=13.0 W=18.0 2-span	234	10/30/2020	6 Tons	MP	1950
Colebrook	190/109	HARVEY SWELL ROAD	E BRANCH MOHAWK RIVER	91-19	Culvert 4 Poor	L=14.0 W=24.0 1-span	336	10/30/2020	E-2	MP	1969
Columbia	228/109	BUNGY ROAD	EAST BRANCH SIMMS STREAM	91-19	Deck 5 Fair Superstructure 5 Fair Substructure 3 Serious	L=17.0 W=24.0 1-span	408	10/13/2020	E-2	CS	1932

2020 MUNICIPAL BRIDGE RED LIST

Town / City	Bridge Number	Facility Carried	Feature Crossed	Est. ADT (Year)	Condition of Deck, Superstructure, Substructure, or Culvert	Total Length (ft); Total Width (ft); No. of Spans	Gross Deck Area (sf)	Date of Most Recent Inspection	Bridge Posting	Structure Type	Year Modified / Year Built
Concord	048/082	WASHINGTON STREET	CANAL INLET	2,922-19	Deck 5 Fair Superstructure 5 Fair Substructure 3 Serious	L=76.0 W=34.3 1-span	2,603	11/24/2020	E-2	IB-C	1975
Concord	163/111	NH 9(LOUDON ROAD)	MERRIMACK RIVER	25,651-19	Deck 4 Poor Superstructure 6 Satisfactory Substructure 5 Fair	L=525.0 W=77.0 4-span	40,425	11/23/2020	NPR	IB-C	1996/1966
Concord	190/067	IRON WORKS ROAD	TURKEY RIVER	1,395-19	Deck 3 Serious Superstructure 3 Serious Substructure 3 Serious	L=15.0 W=29.0 1-span	435	11/16/2020	E-2	CS	1925
Concord	193/027	BIRCHDALE ROAD	BELA BROOK	434-19	Deck 4 Poor Superstructure 4 Poor Substructure 4 Poor	L=22.0 W=24.0 1-span	528	10/20/2020	E-2	CRF	1928
Concord	200/015	HOOKSETT TURNPIKE	BELA BROOK	727-19	Deck 4 Poor Superstructure 4 Poor Substructure 4 Poor	L=16.0 W=24.0 1-span	384	10/20/2020	E-2	CRF	1928
Conway	065/057	CONWAY SCENIC RR	RIVER ROAD	0-80 2,200-15	Deck 5 Fair Superstructure 5 Fair Substructure 4 Poor	L=75.0 W=9.8 8-span	738	11/3/2020	NPR	TB	1931
Cornish	175/143	LEAVITT HILL ROAD	BLOW-ME-DOWN-BROOK	104-19	Deck 4 Poor Superstructure 7 Good Substructure 7 Good	L=23.0 W=25.1 1-span	577	10/8/2019	E-2	IB-BP	1991/1950
Croydon	104/069	BRIGHTON ROAD	BEAVER BROOK	91-19	Culvert 4 Poor	L=16.0 W=18.0 1-span	288	11/17/2020	E-2	MP	1985
Danbury	112/108	BOHONNON ROAD	WILD MEADOW BROOK	91-19	Culvert 3 Serious	L=16.0 W=20.0 1-span	320	7/8/2020	E-2	MP	1960
Danbury	178/057	WALKER BROOK ROAD	FRAZIER BROOK	77-19	Deck 7 Good Superstructure 4 Poor Substructure 6 Satisfactory	L=28.0 W=16.2 1-span	454	7/17/2020	6 Tons	IB-W	1950
Danbury	224/074	JACK WELLS ROAD	FRAZIER BROOK	45-19	Deck 7 Good Superstructure 7 Good Substructure 4 Poor	L=25.0 W=12.5 1-span	313	7/23/2020	NPR	IB-W	2016/1950
Deerfield	139/127	BLAKES HILL ROAD	LAMPREY RIVER	91-19	Deck 5 Fair Superstructure 4 Poor Substructure 5 Fair	L=19.0 W=20.9 1-span	397	10/29/2020	12 Tons	Jack	1930
Dover	057/173	SIXTH STREET	BLACKWATER BROOK	3,125-19	Culvert 4 Poor	L=16.0 W=18.0 1-span	288	9/10/2020	E-2	CRF	1937
Durham	097/109	MILL ROAD	OYSTER RIVER	2,197-19	Culvert 4 Poor	L=17.0 W=26.0 1-span	442	12/8/2020	E-2	MP	1971
Durham	150/065	DURHAM POINT ROAD	CROMMET CREEK	254-19	Deck 5 Fair Superstructure 5 Fair Substructure 4 Poor	L=23.0 W=23.0 1-span	529	12/8/2020	15 Tons	IB-C	1970/1930
Eaton	058/130	POTTER ROAD	SNOW BROOK	91-19	Deck 5 Fair Superstructure 4 Poor Substructure 4 Poor	L=19.0 W=18.2 1-span	346	11/24/2020	E-2	IB-S	1965
Effingham	165/112	SNOW ROAD	SOUTH RIVER	185-19	Culvert 3 Serious	L=32.0 W=20.0 4-span	640	11/24/2020	E-2	MP	1972

2020 MUNICIPAL BRIDGE RED LIST

Town / City	Bridge Number	Facility Carried	Feature Crossed	Est. ADT (Year)	Condition of Deck, Superstructure, Substructure, or Culvert	Total Length (ft); Total Width (ft); No. of Spans	Gross Deck Area (sf)	Date of Most Recent Inspection	Bridge Posting	Structure Type	Year Modified / Year Built
Effingham	166/082	GRANITE ROAD	SOUTH RIVER	91-19	Deck 5 Fair Superstructure 2 Critical Substructure 5 Fair	L=36.0 W=18.5 2-span	666	11/24/2020	BRC	IB-C	1950/1920
Enfield	198/103	OAK HILL ROAD	GRAFTON POND OUTLET	91-19	Culvert 3 Serious	L=11.0 W=21.0 1-span	231	9/14/2020	NPR	MP	1994
Exeter	068/083	GARRISON LANE	LITTLE RIVER	15-19	Deck 4 Poor Superstructure 6 Satisfactory Substructure 4 Poor	L=27.0 W=18.0 1-span	486	8/12/2020	NPR	IB-W	1976/1930
Farmington	071/089	HORNETOWN ROAD	MAD RIVER	88-18	Deck 5 Fair Superstructure 3 Serious Substructure 5 Fair	L=24.0 W=24.0 1-span	576	12/2/2020	NPR	IB-BP	1984
Farmington	076/135	SPRING STREET	COCHECO RIVER	793-18	Deck 4 Poor Superstructure 6 Satisfactory Substructure 5 Fair	L=39.0 W=30.0 1-span	1,170	12/4/2020	E-2	CTB	1926
Farmington	080/108	RIVER ROAD	MAD RIVER	104-18	Deck 4 Poor Superstructure 3 Serious Substructure 5 Fair	L=35.0 W=24.3 1-span	852	12/2/2020	BRC	IB-BP	1986
Farmington	142/050	SHEEPBORO ROAD	BERRYS RIVER	20-87	Deck 6 Satisfactory Superstructure 6 Satisfactory Substructure 4 Poor	L=21.5 W=20.0 1-span	430	12/4/2020	E-2	IB-W	2007/1983
Fitzwilliam	147/054	TEMPLETON TURNPIKE	PRIEST BROOK	65-19	Culvert 2 Critical	L=10.0 W=22.0 1-span	220	11/30/2020	NPR	MP	1987
Fitzwilliam	147/080	TEMPLETON TURNPIKE	PRIEST BROOK	65-19	Culvert 2 Critical	L=21.0 W=18.0 3-span	378	11/30/2020	3 Tons	MP	1984
Fracestown	091/142	OLD COUNTY RD N	COLLINS BROOK	88-18	Culvert 3 Serious	L=30.0 W=15.0 2-span	450	10/23/2020	E-2	MP	1981
Fracestown	119/059	GRESSY HILL ROAD	RAND BROOK	88-18	Deck 7 Good Superstructure 4 Poor Substructure 5 Fair	L=31.0 W=16.0 1-span	496	10/22/2020	10 Tons	IB-W	1940
Franconia	057/083	LAFAYETTE ROAD	HAM BRANCH	497-18	Deck 6 Satisfactory Superstructure 4 Poor Substructure 6 Satisfactory	L=52.0 W=22.2 1-span	1,154	11/13/2020	E-2	IB-G	1979/1920
Fremont	106/076	SCRIBNER ROAD	EXETER RIVER	265-19	Deck 3 Serious Superstructure 5 Fair Substructure 5 Fair	L=47.0 W=24.3 1-span	1,142	10/23/2020	E-2	IB-C	1941
Fremont	155/133	MARTIN ROAD	PISCASSIC RIVER	583-19	Deck 4 Poor Superstructure 6 Satisfactory Substructure 3 Serious	L=18.0 W=20.5 1-span	369	10/23/2020	15 Tons	IB-C	1930
Gilford	139/093	RECREATION TRAIL	GUNSTOCK RIVER	0-00	Deck 7 Good Superstructure 7 Good Substructure 4 Poor	L=42.0 W=10.5 1-span	441	8/6/2020	NPR	TB-C	1995
Gilsum	097/139	BANKS ROAD	HAYWARD BROOK	88-18	Culvert 3 Serious	L=12.0 W=21.0 1-span	252	12/8/2020	NPR	MP	1994
Goshen	082/083	BALL PARK ROAD	TROW BROOK	88-18	Deck 6 Satisfactory Superstructure 5 Fair Substructure 3 Serious	L=15.0 W=18.0 1-span	270	12/1/2020	NPR	IB-BP	1994/1930

2020 MUNICIPAL BRIDGE RED LIST

Town / City	Bridge Number	Facility Carried	Feature Crossed	Est. ADT (Year)	Condition of Deck, Superstructure, Substructure, or Culvert	Total Length (ft); Total Width (ft); No. of Spans	Gross Deck Area (sf)	Date of Most Recent Inspection	Bridge Posting	Structure Type	Year Modified / Year Built
Goshen	084/077	LEMPSTER COACH RD	TROW BROOK	88-18	Deck 8 Very Good Superstructure 6 Satisfactory Substructure 4 Poor	L=25.0 W=18.0 1-span	450	12/1/2020	NPR	IB-BP	1999/1940
Grantham	083/108	OLDE FARMS ROAD	SAWYER BROOK	91-19	Culvert 3 Serious	L=13.0 W=20.0 1-span	260	11/17/2020	NPR	MP	1965
Grantham	108/147	FRYE LANE	STONY BROOK	50-00	Culvert 3 Serious	L=12.0 W=12.0 1-span	144	11/17/2020	NPR	MP	1972
Greenfield	151/089	SCHOOL HOUSE RD	BROOK	88-18	Culvert 1 Closed - Failing	L=14.0 W=14.0 1-span	196	10/28/2020	BRC	MP	1988
Greenville	075/114	WILTON ROAD	SOUHEGAN RIVER	1,769-18	Deck 7 Good Superstructure 5 Fair Substructure 4 Poor	L=173.0 W=32.0 1-span	5,536	11/13/2020	E-2	HT	1986/1938
Hancock	100/046	WINDY ROW ROAD	MCDOWELL RESERVOIR	236-19	Deck 5 Fair Superstructure 4 Poor Substructure 5 Fair	L=224.0 W=21.0 4-span	4,704	8/27/2020	BRC	IB-C	1950
Hancock	107/074	MIDDLE HANCOCK RD	SMALL BROOK	91-19	Culvert 4 Poor	L=13.0 W=22.0 1-span	286	11/12/2020	NPR	MP	1982
Hanover	056/089	RESERVOIR ROAD	CAMP BROOK	519-18	Culvert 4 Poor	L=12.0 W=21.0 1-span	252	12/4/2020	E-2	MP-A	1940
Hanover	116/097	HANOVER CENTER RD	MONAHAN BROOK	1,176-18	Deck 4 Poor Superstructure 4 Poor Substructure 6 Satisfactory	L=12.0 W=23.7 1-span	284	12/4/2020	E-2	CRF	1929
Hanover	118/080	RUDDSBORO ROAD	MINK BROOK	88-18	Culvert 4 Poor	L=37.0 W=22.0 2-span	814	12/4/2020	E-2	MP-A	1940
Harrisville	061/060	SOUTH ROAD	MINNEWAWA BROOK	88-18	Deck 6 Satisfactory Superstructure 6 Satisfactory Substructure 4 Poor	L=31.0 W=20.2 1-span	626	11/3/2020	NPR	PTB	1950
Haverhill	095/046	FLAT IRON ROAD	NORTH BRANCH	88-18	Culvert 4 Poor	L=12.0 W=12.0 1-span	144	10/2/2020	E-2	MP	1985
Hill	131/080	BUNKER HILL ROAD	NEEDLE SHOP BROOK	91-19	Culvert 4 Poor	L=17.0 W=17.0 1-span	289	7/9/2020	E-2	MP	1978
Hill	171/105	SHOP ROAD	NEEDLE SHOP BROOK	49-18	Deck 6 Satisfactory Superstructure 3 Serious Substructure 5 Fair	L=35.0 W=12.2 1-span	427	7/29/2020	3 Tons	IB-W	1930
Hillsborough	061/139	COOLEGE ROAD	BEARDS BROOK	88-18	Deck 5 Fair Superstructure 3 Serious Substructure 5 Fair	L=26.0 W=24.0 1-span	624	10/1/2020	E-2	IB-C	1970
Hillsborough	088/093	GLEASON FALLS ROAD	BEARDS BROOK	88-18	Culvert 4 Poor	L=34.0 W=12.0 1-span	408	9/29/2020	6 Tons	MA	1900
Hillsborough	100/070	JONES ROAD	BEARDS BROOK	88-18	Culvert 4 Poor	L=45.0 W=12.0 2-span	540	9/29/2020	6 Tons	MA	1900

2020 MUNICIPAL BRIDGE RED LIST

Town / City	Bridge Number	Facility Carried	Feature Crossed	Est. ADT (Year)	Condition of Deck, Superstructure, Substructure, or Culvert	Total Length (ft); Total Width (ft); No. of Spans	Gross Deck Area (sf)	Date of Most Recent Inspection	Bridge Posting	Structure Type	Year Modified / Year Built
Hillsborough	146/102	COLBY ROAD	NELSON BROOK	88-18	Culvert 3 Serious	L=13.0 W=16.0 1-span	208	10/15/2020	E-2	MS	1900
Hillsborough	154/113	BOG ROAD	SAND BROOK	88-18	Culvert 3 Serious	L=11.0 W=16.0 1-span	176	10/15/2020	E-2	MP	1985
Hillsborough	158/080	RED FOX CROSSING	NELSON BROOK	100-93	Culvert 1 Closed - Failing	L=14.0 W=18.0 1-span	252	10/1/2020	BRC	MP	1984
Hillsborough	171/064	CONTOCOOK FALLS R	CONTOCOOK RIVER	459-18	Deck 6 Satisfactory Superstructure 4 Poor Substructure 7 Good	L=224.0 W=29.0 2-span	6,496	8/21/2020	C-2	TPG	1991/1933
Hopkinton	057/111	NH127	PENSTOCK (UNIT 1)	3,474-19	Culvert 2 Critical	L=10.0 W=23.0 1-span	230	6/16/2014	NPR	MP	1980
Hopkinton	154/136	BROAD COVE ROAD	DOLF BROOK	88-18	Culvert 4 Poor	L=12.0 W=22.0 1-span	264	11/16/2020	NPR	MP	1990
Hudson	116/080	NH 3A	FIRST BROOK	20,434-19	Culvert 4 Poor	L=10.0 W=44.0 1-span	440	6/10/2020	NPR	MP	1987
Jaffrey	159/094	NUTTING ROAD	CONTOCOOK RIVER	1,877-19	Deck 4 Poor Superstructure 4 Poor Substructure 6 Satisfactory	L=43.0 W=27.0 1-span	1,161	7/21/2020	E-2	MA	1905
Jefferson	104/078	LARCOMB ROAD	ISRAEL RIVER OVERFLOW	88-18	Culvert 4 Poor	L=10.0 W=12.0 1-span	120	10/19/2020	NPR	MP	1979
Keene	079/080	WHITCOMB MILLS RD	WHITE BROOK	776-18	Deck 5 Fair Superstructure 5 Fair Substructure 4 Poor	L=23.0 W=16.3 1-span	376	11/12/2020	6 Tons	IB-C	1940
Keene	090/101	MAPLE AVE	BLACK BROOK	3,303-18	Culvert 3 Serious	L=23.0 W=22.0 3-span	506	11/12/2020	E-2	MP	1961
Keene	091/099	SUMMIT ROAD	BLACK BROOK	2,391-18	Culvert 4 Poor	L=12.0 W=24.0 1-span	288	11/12/2020	E-2	CB	1979/1948
Keene	118/051	NH 10	ASH SWAMP BROOK	18,780-18	Deck 4 Poor Superstructure 4 Poor Substructure 6 Satisfactory	L=21.0 W=25.0 1-span	525	11/12/2020	E-2	CB	1941
Keene	140/075	CHURCH STREET	BEAVER BROOK	775-18	Deck 5 Fair Superstructure 5 Fair Substructure 3 Serious	L=20.0 W=37.0 1-span	740	11/24/2020	E-2	IB-C	1940
Keene	140/078	SPRING STREET	BEAVER BROOK	604-18	Deck 4 Poor Superstructure 4 Poor Substructure 4 Poor	L=22.0 W=34.2 1-span	752	11/24/2020	E-2	CTB	1923
Keene	140/079	BEAVER STREET	BEAVER BROOK	2,855-18	Deck 4 Poor Superstructure 4 Poor Substructure 3 Serious	L=15.0 W=40.5 1-span	608	11/24/2020	E-2	CS	1923
Keene	142/092	GEORGE STREET	BEAVER BROOK	486-18	Deck 4 Poor Superstructure 4 Poor Substructure 3 Serious	L=17.0 W=40.0 1-span	680	11/25/2020	E-2	CS	1923

2020 MUNICIPAL BRIDGE RED LIST

Town / City	Bridge Number	Facility Carried	Feature Crossed	Est. ADT (Year)	Condition of Deck, Superstructure, Substructure, or Culvert	Total Length (ft); Total Width (ft); No. of Spans	Gross Deck Area (sf)	Date of Most Recent Inspection	Bridge Posting	Structure Type	Year Modified / Year Built
Keene	173/135	FERRY BROOK ROAD	FERRY BROOK	59-18	Deck 5 Fair Superstructure 5 Fair Substructure 4 Poor	L=14.5 W=17.1 1-span	248	11/25/2020	E-2	CS	1940
Laconia	121/037	ACADEMY STREET	DURKEE BROOK	1,298-18	Deck 4 Poor Superstructure 3 Serious Substructure 5 Fair	L=22.0 W=67.0 1-span	1,474	10/7/2020	E-2	IB-C	1930
Laconia	123/049	RECREATION TRAIL	WINNIPESAUKEE RIVER	0-08	Deck 4 Poor Superstructure 5 Fair Substructure 6 Satisfactory	L=131.0 W=8.0 2-span	1,048	10/9/2020	NPR	IB-C	1960
Laconia	135/128	US 3,WEIRS BLVD	LANGLEY BROOK	9,518-18	Deck 4 Poor Superstructure 4 Poor Substructure 5 Fair	L=12.0 W=60.0 1-span	720	10/12/2020	NPR	IB-C	1933
Lancaster	218/076	MCGARY HILL ROAD	BONE BROOK	97-18	Culvert 4 Poor	L=14.0 W=19.0 2-span	266	10/30/2020	E-2	MP	1953
Landaff	074/159	SYM NOYES ROAD	MILL BROOK	88-18	Culvert 3 Serious	L=13.7 W=12.0 1-span	164	11/20/2020	E-2	MP	2001
Landaff	119/118	GALE CHANDLER ROAD	MILL BROOK	88-18	Culvert 4 Poor	L=10.3 W=16.0 1-span	165	11/20/2020	NPR	MP	1980
Landaff	138/134	MERRILL MT ROAD	MILL BROOK	88-18	Deck 7 Good Superstructure 7 Good Substructure 3 Serious	L=14.0 W=15.9 1-span	223	11/20/2020	E-2	CRF	1922
Langdon	161/105	CRANE BROOK ROAD	COLD RIVER	445-19	Deck 4 Poor Superstructure 7 Good Substructure 7 Good	L=94.0 W=27.0 2-span	2,538	10/1/2019	E-2	IB-C	1964
Lebanon	062/117	NH 12A	NHRR	9,440-19	Deck 4 Poor Superstructure 5 Fair Substructure 6 Satisfactory	L=145.0 W=27.7 3-span	4,017	7/30/2020	E-2	IB-C	1949
Lebanon	066/059	TRUE'S BROOK ROAD	BLOODS BROOK	1,148-19	Deck 3 Serious Superstructure 5 Fair Substructure 6 Satisfactory	L=65.0 W=22.0 2-span	1,430	7/10/2020	E-2	IB-C	1986/1952
Lebanon	100/110	US 4,MECHANIC ST	MASCOMA RIVER	14,555-19	Deck 4 Poor Superstructure 7 Good Substructure 6 Satisfactory	L=89.0 W=72.5 1-span	6,453	7/30/2020	E-2	IB-C	1977
Lebanon	121/117	NH120,PARK LOT, PED	NHRR(ABD)	6,036-19	Deck 4 Poor Superstructure 4 Poor Substructure 5 Fair	L=28.0 W=61.3 1-span	1,716	7/28/2020	E-2	PVS	1969
Lempster	096/081	OLDS ROAD	DODGE BROOK	91-19	Deck 3 Serious Superstructure 5 Fair Substructure 6 Satisfactory	L=28.0 W=17.4 1-span	487	9/3/2019	E-2	IB-BP	1998/1976
Lisbon	063/078	SCHOOL STREET	AMMONOOSUC RIVER	2,201-18	Deck 4 Poor Superstructure 7 Good Substructure 6 Satisfactory	L=222.0 W=36.2 3-span	8,037	11/24/2020	E-2	IB-C	1986/1960
Lisbon	088/125	PLAINS ROAD	MILL BROOK	88-18	Deck 6 Satisfactory Superstructure 4 Poor Substructure 6 Satisfactory	L=27.0 W=22.0 1-span	594	11/25/2020	E-2	IB-C	1975
Londonderry	070/135	HALL ROAD	LITTLE COHAS BROOK	1,991-18	Deck 6 Satisfactory Superstructure 6 Satisfactory Substructure 4 Poor	L=24.0 W=32.0 1-span	768	11/19/2020	E-2	CS	1974

2020 MUNICIPAL BRIDGE RED LIST

Town / City	Bridge Number	Facility Carried	Feature Crossed	Est. ADT (Year)	Condition of Deck, Superstructure, Substructure, or Culvert	Total Length (ft); Total Width (ft); No. of Spans	Gross Deck Area (sf)	Date of Most Recent Inspection	Bridge Posting	Structure Type	Year Modified / Year Built
Londonderry	077/151	STOKES ROAD	LITTLE COHAS BROOK	35-18	Deck 4 Poor Superstructure 4 Poor Substructure 4 Poor	L=28.0 W=18.0 1-span	504	11/19/2020	15 Tons	CS	1930
Loudon	054/065	WALES BRIDGE ROAD	SOUCCOOK RIVER	342-18	Deck 4 Poor Superstructure 4 Poor Substructure 6 Satisfactory	L=146.0 W=29.0 3-span	4,234	12/7/2020	E-2	CRF	1934
Lyme	113/147	PINNACLE ROAD	TROUT BROOK	239-18	Culvert 3 Serious	L=19.0 W=16.0 2-span	304	11/30/2020	E-2	MP	1980
Lyme	141/094	FLINT HILL ROAD	GRANT BROOK	88-18	Culvert 3 Serious	L=19.0 W=14.0 2-span	266	11/6/2020	E-2	MP	1979
Madbury	056/072	NUTE ROAD	BELLAMY RIVER	168-18	Culvert 4 Poor	L=15.0 W=15.0 1-span	225	8/18/2020	E-2	MP	1960
Madbury	160/086	FRESHET ROAD	JOHNSON CREEK	407-18	Culvert 3 Serious	L=14.2 W=18.0 1-span	256	8/18/2020	E-2	MP	1974
Manchester	107/072	SALMON STREET EB	MERRIMACK R, PAR, RD, RAMP	11,821-18 7,800-13 7,500-03	Deck 4 Poor Superstructure 5 Fair Substructure 5 Fair	L=1023.0 W=33.7 8-span	34,441	9/17/2020	NPR	IB-C	1999/1970
Manchester	151/065	US 3, NH 3A	I-293, NH 3A, PAR, MERR R	24,531-18 61,000-15 36,500-12	Deck 4 Poor Superstructure 5 Fair Substructure 5 Fair	L=1186.0 W=59.0 14-span	69,974	9/14/2020	NPR	DT	1995/1923
Manchester	188/092	GOFFS FALLS ROAD	PAR(ABD)	4,511-18	Deck 4 Poor Superstructure 6 Satisfactory Substructure 4 Poor	L=88.0 W=35.0 3-span	3,080	11/18/2020	NPR	IB-C	1979/1948
Marlborough	128/077	OLD DUBLIN ROAD	MOUNTAIN BROOK	88-18	Deck 5 Fair Superstructure 5 Fair Substructure 4 Poor	L=22.0 W=20.2 1-span	444	8/18/2020	E-2	IB-C	1965
Meredith	106/128	BLAKE ROAD	BROOK	55-18	Deck 4 Poor Superstructure 4 Poor Substructure 7 Good	L=13.0 W=23.0 1-span	299	11/30/2020	E-2	CS	1929
Meredith	180/144	PARKING LOT ACCESS	WAUKEWAN LK OUTLET	200-01	Deck 4 Poor Superstructure 7 Good Substructure 7 Good	L=27.5 W=15.8 1-span	433	11/30/2020	15 Tons	TB	2000
Merrimack	112/115	RECREATION TRAIL	SOUHEGAN RIVER	0-11	Deck 7 Good Superstructure 3 Serious Substructure 8 Very Good	L=136.0 W=6.0 1-span	816	6/30/2020	NPR	HT	2011
Merrimack	116/120	US 3	SOUHEGAN RIVER	13,596-19	Deck 5 Fair Superstructure 4 Poor Substructure 5 Fair	L=113.0 W=42.0 2-span	4,746	6/30/2020	E-2	MA	1934/1921
Merrimack	118/135	US 3	BABOOSIC BROOK	14,565-19	Culvert 4 Poor	L=30.0 W=32.0 1-span	960	6/30/2020	E-2	CACUL	1933
Milan	219/126	CHICKWOLNEP Y ROAD	CHICKWOLNEP STREAM	88-18	Deck 5 Fair Superstructure 4 Poor Substructure 5 Fair	L=38.8 W=16.0 1-span	621	10/23/2020	6 Tons	IB-W	1950

2020 MUNICIPAL BRIDGE RED LIST

Town / City	Bridge Number	Facility Carried	Feature Crossed	Est. ADT (Year)	Condition of Deck, Superstructure, Substructure, or Culvert	Total Length (ft); Total Width (ft); No. of Spans	Gross Deck Area (sf)	Date of Most Recent Inspection	Bridge Posting	Structure Type	Year Modified / Year Built
Milan	254/038	STEARNS BROOK ROAD	STEARNS BROOK	88-18	Deck 4 Poor Superstructure 5 Fair Substructure 5 Fair	L=39.0 W=16.0 1-span	624	10/23/2020	NPR	BAIB	1950
Milford	089/106	MASON ROAD	GREAT BROOK	3,506-19	Culvert 4 Poor	L=11.0 W=22.0 1-span	242	6/16/2020	E-2	MP	1982
Milford	103/163	HARTSHORN ROAD	HARTSHORN BROOK	28-19	Culvert 3 Serious	L=18.0 W=17.0 2-span	306	6/22/2020	6 Tons	MS	1910
Milton - Lebanon	168/152	TOWNHOUSE ROAD	NORTHEAST POND	489-18	Deck 0 Failed - Closed Superstructure 0 Failed - Closed Substructure 0 Failed - Closed	L=94.0 W=26.2 4-span	2,463	12/3/2020	BRC	TB	1948
Milton	190/101	WINDING ROAD	LYMAN BROOK	88-18	Deck 5 Fair Superstructure 4 Poor Substructure 4 Poor	L=21.0 W=33.5 1-span	704	12/3/2020	E-2	IB-BP	1995
Mont Vernon	142/089	BEAVER BROOK ROAD	BEAVER BROOK	827-18	Deck 4 Poor Superstructure 4 Poor Substructure 7 Good	L=30.0 W=22.0 1-span	660	10/29/2020	E-2	CS	1932
Nashua	139/115	CANAL STREET	NASHUA RIVER	16,809-18	Deck 6 Satisfactory Superstructure 6 Satisfactory Substructure 4 Poor	L=160.0 W=54.0 2-span	8,640	11/18/2020	E-2	CA	1928
Nelson	142/126	OLD STODDARD ROAD	BAILEY BROOK	91-19	Culvert 2 Critical	L=13.5 W=16.0 1-span	216	7/25/2019	NPR	MP	1988
New Boston	091/155	DOUGHERTY LANE	MID BR PISCATAQUOG RIVER	88-18	Deck 8 Very Good Superstructure 8 Very Good Substructure 1 Closed - Failing	L=22.0 W=20.0 1-span	440	10/28/2020	BRC	CRF-P	2004
New Hampton	061/069	BROOK ROAD	BLAKE BROOK	88-18	Deck 6 Satisfactory Superstructure 6 Satisfactory Substructure 4 Poor	L=22.0 W=15.3 1-span	337	12/1/2020	12 Tons	TB	1960/1920
New Ipswich	108/070	TAYLOR ROAD	WEST BR SOUHEGAN RIVER	88-18	Culvert 3 Serious	L=10.0 W=18.0 1-span	180	8/13/2020	BRC	MP	1981
Newport	086/095	CHANDLER MILL ROAD	CUTTS BROOK	544-19	Deck 4 Poor Superstructure 4 Poor Substructure 5 Fair	L=20.0 W=20.0 1-span	400	7/31/2020	E-2	IB-BP	1973
Newport	097/139	GREENWOOD ROAD	DODGE BROOK	91-19	Deck 1 Closed - Failing Superstructure 1 Closed - Failing Substructure 1 Closed - Failing	L=18.0 W=23.6 1-span	424	7/31/2020	BRC	IB-BP	1989
Newport	154/129	SAND HILL ROAD	BROOK	184-19	Deck 3 Serious Superstructure 2 Critical Substructure 5 Fair	L=27.0 W=24.3 1-span	656	7/31/2020	E-2	IB-BP	1984
Newport	177/117	PARADISE ROAD	SUGAR RIVER	91-19	Deck 1 Closed - Failing Superstructure 1 Closed - Failing Substructure 1 Closed - Failing	L=39.0 W=18.0 1-span	702	7/2/2020	BRC	IB-BP	1976

2020 MUNICIPAL BRIDGE RED LIST

Town / City	Bridge Number	Facility Carried	Feature Crossed	Est. ADT (Year)	Condition of Deck, Superstructure, Substructure, or Culvert	Total Length (ft); Total Width (ft); No. of Spans	Gross Deck Area (sf)	Date of Most Recent Inspection	Bridge Posting	Structure Type	Year Modified / Year Built
Newton	053/105	WILDERS GROVE RD	COUNTRY POND	470-18	Culvert 2 Critical	L=12.0 W=12.0 2-span	144	12/9/2020	NPR	MP	1989
Northwood	095/113	BOW LAKE ROAD	SHERBURNE BROOK	576-18	Deck 3 Serious Superstructure 3 Serious Substructure 3 Serious	L=14.0 W=25.0 1-span	350	10/8/2020	E-2	CS	1938
Orange	107/046	BROCK HILL ROAD	BROWN BROOK	88-18	Culvert 4 Poor	L=17.2 W=24.0 1-span	413	12/7/2020	E-2	MP	1980
Orford	080/120	ARCHERTOWN ROAD	JACOBS BROOK	395-18	Deck 4 Poor Superstructure 5 Fair Substructure 5 Fair	L=52.0 W=18.3 1-span	952	10/6/2020	E-2	IB-C	1930
Orford	087/108	HIGH BRIDGE ROAD	ARCHERTOWN BROOK	88-18	Deck 1 Closed - Failing Superstructure 1 Closed - Failing Substructure 1 Closed - Failing	L=24.0 W=14.0 1-span	336	11/30/2020	BRC	IB-W	1940
Orford	114/133	TOWN ROAD #100	ARCHERTOWN BROOK	88-18	Culvert 3 Serious	L=13.0 W=12.0 1-span	156	10/6/2020	E-2	MP	1997
Peterborough	092/089	MAIN STREET	CONTOCOOK RIVER	8,499-18	Deck 3 Serious Superstructure 3 Serious Substructure 5 Fair	L=86.0 W=41.5 1-span	3,569	11/4/2020	3 Tons	CRF	1940
Peterborough	132/134	SLAB ROAD	OTTER BROOK	88-18	Deck 5 Fair Superstructure 5 Fair Substructure 3 Serious	L=26.0 W=20.0 1-span	520	11/4/2020	E-2	Jack	1940
Pittsburg	134/057	HILL ROAD	PERRY STREAM	239-18	Deck 7 Good Superstructure 5 Fair Substructure 4 Poor	L=78.0 W=18.3 2-span	1,427	10/7/2020	E-2	TB-C	1991/1860
Portsmouth	198/107	CATE STREET	HODGSON BROOK	1,448-18	Deck 2 Critical Superstructure 5 Fair Substructure 6 Satisfactory	L=37.0 W=28.0 1-span	1,036	12/8/2020	15 Tons	IB-C	1940
Portsmouth	231/103	MAPLEWOOD AVENUE	NORTH MILL POND	6,603-18	Culvert 3 Serious	L=25.0 W=32.0 1-span	800	12/8/2020	E-2	MA-CA	1976/1940
Randolph	080/047	DURAND ROAD	MOOSE RIVER	88-18	Deck 4 Poor Superstructure 4 Poor Substructure 4 Poor	L=14.0 W=28.0 1-span	392	11/12/2020	E-2	CB	1920
Richmond	065/083	WHIPPLE HILL ROAD	ROARING BROOK	233-18	Deck 6 Satisfactory Superstructure 4 Poor Substructure 6 Satisfactory	L=43.0 W=20.5 3-span	882	12/2/2020	NPR	IB-BP	1983/1950
Richmond	155/066	TULLY BROOK ROAD	TULLY BROOK	88-18	Culvert 4 Poor	L=14.0 W=18.0 1-span	252	12/2/2020	15 Tons	MP	1990
Rindge	154/069	WELLINGTON ROAD	CONVERSEVILLE BROOK	879-19	Culvert 3 Serious	L=28.0 W=24.0 2-span	672	7/20/2020	3 Tons	MP	1950
Rollinsford	090/052	OLD MILL LANE	ROLLINS BROOK	201-18	Deck 4 Poor Superstructure 2 Critical Substructure 3 Serious	L=21.0 W=18.5 1-span	389	8/18/2020	NPR	TB	1900

2020 MUNICIPAL BRIDGE RED LIST

Town / City	Bridge Number	Facility Carried	Feature Crossed	Est. ADT (Year)	Condition of Deck, Superstructure, Substructure, or Culvert	Total Length (ft); Total Width (ft); No. of Spans	Gross Deck Area (sf)	Date of Most Recent Inspection	Bridge Posting	Structure Type	Year Modified / Year Built
Rumney	093/082	BUFFALO ROAD	BROOK	454-18	Culvert 2 Critical	L=13.0 W=21.0 1-span	273	10/8/2020	E-2	MP	1972
Salem	115/097	BRIDGE STREET	SPICKET RIVER	5,776-18	Deck 4 Poor Superstructure 4 Poor Substructure 4 Poor	L=29.0 W=35.0 1-span	1,015	11/20/2020	E-2	Jack	1959/1900
Sanbornnton	118/089	BROOK ROAD	SALMON BROOK	88-18	Deck 8 Very Good Superstructure 8 Very Good Substructure 4 Poor	L=35.0 W=16.0 1-span	560	11/30/2020	NPR	CS	2012/1900
Sharon	071/056	SWAMP ROAD	GRIDLEY RIVER	91-19	Deck 7 Good Superstructure 7 Good Substructure 4 Poor	L=20.0 W=16.0 1-span	320	7/22/2020	NPR	IB-G	1991/1938
Shelburne	114/104	VILLAGE ROAD	CLEMENT BROOK	55-18	Deck 5 Fair Superstructure 5 Fair Substructure 4 Poor	L=45.0 W=30.1 2-span	1,354	10/28/2020	E-2	CS	1971/1929
South Hampton	069/066	HILLDALE AVE	POWWOW RIVER	201-18	Deck 4 Poor Superstructure 4 Poor Substructure 4 Poor	L=31.0 W=18.6 1-span	577	10/28/2020	15 Tons	IB-C	1920
South Hampton	099/062	WHITEHALL ROAD	POWWOW RIVER	605-18	Deck 6 Satisfactory Superstructure 4 Poor Substructure 7 Good	L=33.0 W=22.0 1-span	726	10/28/2020	E-2	IB-C	1976
Springfield	071/138	GEORGE HILL ROAD	GOVE BROOK	88-18	Culvert 4 Poor	L=12.0 W=21.0 1-span	252	9/18/2020	E-2	MP	1970
Stark	068/173	LEIGHTON MEADOW RD	PHILLIPS BROOK	88-18	Deck 5 Fair Superstructure 5 Fair Substructure 3 Serious	L=40.0 W=13.6 1-span	544	10/29/2020	6 Tons	CTB	1970/1940
Stewartstown	109/100	BISHOP BROOK ROAD	CEDAR BROOK	88-18	Culvert 4 Poor	L=12.0 W=19.0 1-span	228	10/7/2020	E-2	MP	1960
Stoddard	115/126	KINGS HIGHWAY	KENNEDY BROOK	88-18	Culvert 2 Critical	L=12.0 W=22.5 2-span	270	8/31/2020	10 Tons	MP	1980
Strafford	057/135	BARN DOOR GAP ROAD	BIG RIVER	88-18	Culvert 3 Serious	L=14.0 W=16.0 1-span	224	8/10/2020	E-2	MP	1984
Sugar Hill	202/128	CRANE HILL ROAD	GALE RIVER	88-18	Deck 4 Poor Superstructure 4 Poor Substructure 4 Poor	L=108.0 W=18.9 1-span	2,041	11/23/2020	8 Tons	HT	1960/1928
Sugar Hill	208/125	STREETER POND ROAD	INDIAN CREEK	474-18	Culvert 3 Serious	L=11.5 W=16.0 1-span	184	11/23/2020	NPR	CRF-P	2010
Sunapee	069/069	TRASK BROOK ROAD	WENDELL BROOK	88-18	Culvert 4 Poor	L=11.0 W=16.0 2-span	176	9/17/2020	NPR	MP	1983
Swanzy	098/122	CHRISTIAN HILL RD	NHRR(ABD)	1,972-19	Deck 1 Closed - Failing Superstructure 1 Closed - Failing Substructure 1 Closed - Failing	L=74.0 W=20.8 3-span	1,539	8/5/2020	BRC	TB	1960/1930

2020 MUNICIPAL BRIDGE RED LIST

Town / City	Bridge Number	Facility Carried	Feature Crossed	Est. ADT (Year)	Condition of Deck, Superstructure, Substructure, or Culvert	Total Length (ft); Total Width (ft); No. of Spans	Gross Deck Area (sf)	Date of Most Recent Inspection	Bridge Posting	Structure Type	Year Modified / Year Built
Tamworth	037/157	SCOTT ROAD	CHOCORUA RIVER	88-18	Culvert 3 Serious	L=11.0 W=14.0 1-span	154	12/3/2020	NPR	MP	1995
Tamworth	168/070	MOUNTAIN ROAD	COLD BROOK	57-18	Deck 6 Satisfactory Superstructure 4 Poor Substructure 5 Fair	L=38.0 W=16.0 1-span	608	12/3/2020	E-2	IB-W	1983/1900
Temple	107/117	POWERS ROAD	BLOOD BROOK	91-19	Deck 4 Poor Superstructure 5 Fair Substructure 3 Serious	L=24.0 W=16.0 1-span	384	6/17/2020	3 Tons	IB-C	1920
Temple	116/139	PUTNAM ROAD	BROOK	91-19	Deck 6 Satisfactory Superstructure 6 Satisfactory Substructure 3 Serious	L=25.0 W=17.0 1-span	425	6/15/2020	6 Tons	IB-C	1930
Temple	117/138	PUTNAM ROAD	BROOK OVERFLOW	91-19	Deck 5 Fair Superstructure 6 Satisfactory Substructure 4 Poor	L=15.0 W=19.0 1-span	285	6/15/2020	6 Tons	IB-C	1930
Troy	093/084	PROSPECT STREET	BROOK	245-18	Deck 6 Satisfactory Superstructure 6 Satisfactory Substructure 4 Poor	L=19.0 W=23.7 1-span	450	12/2/2020	15 Tons	IB-C	1940
Wakefield NH-Acton,ME	186/118	CANAL ROAD	GREAT EAST LAKE OUTLET	459-18	Deck 4 Poor Superstructure 4 Poor Substructure 4 Poor	L=19.0 W=25.3 1-span	481	9/15/2020	3 Tons	MA	1920
Wakefield	290/064	MAPLE STREET	BRANCH RIVER	88-18	Deck 1 Closed - Failing Superstructure 1 Closed - Failing Substructure 1 Closed - Failing	L=35.0 W=22.3 1-span	781	9/15/2020	BRC	CTB	1972/1940
Walpole	122/067	MAIN STREET	OLD MILL POND BROOK	3,055-18	Culvert 4 Poor	L=10.0 W=40.0 1-span	400	11/19/2020	E-2	MP	1979
Walpole	213/076	WENTWORTH ROAD	HOUGHTON BROOK	134-18	Culvert 4 Poor	L=18.0 W=18.0 1-span	324	11/19/2020	NPR	MP-A	1955
Warner	189/099	NORTH VILLAGE ROAD	SILVER BROOK	88-18	Culvert 4 Poor	L=13.0 W=18.0 1-span	234	10/29/2020	E-2	MP	1979
Warren	106/086	LUND LANE	ORE HILL BROOK	88-18	Culvert 3 Serious	L=17.0 W=18.0 1-span	306	10/5/2020	E-2	MP	1970
Warren	120/058	FISH HATCHERY ROAD	PATCH BROOK	62-18	Deck 4 Poor Superstructure 4 Poor Substructure 4 Poor	L=33.0 W=23.3 1-span	769	12/1/2020	E-2	Jack	1930
Weare	082/045	LULL ROAD	PEACOCK BROOK	112-18	Culvert 3 Serious	L=10.0 W=22.0 1-span	220	9/18/2020	E-2	MP	1973
Weare	084/040	OLD FRANCISTOWN RD	PEACOCK BROOK	258-18	Culvert 3 Serious	L=11.0 W=21.0 1-span	231	9/18/2020	E-2	MP	1973
Weare	110/150	RIVER ROAD	PISCATAQUOG RIVER	1,989-18	Deck 4 Poor Superstructure 3 Serious Substructure 5 Fair	L=117.0 W=29.5 1-span	3,452	11/16/2020	NPR	LT	1997/1940

2020 MUNICIPAL BRIDGE RED LIST

Town / City	Bridge Number	Facility Carried	Feature Crossed	Est. ADT (Year)	Condition of Deck, Superstructure, Substructure, or Culvert	Total Length (ft); Total Width (ft); No. of Spans	Gross Deck Area (sf)	Date of Most Recent Inspection	Bridge Posting	Structure Type	Year Modified / Year Built
Webster	066/113	WHITE PLAINS ROAD	MEADOW BROOK	496-18	Culvert 2 Critical	L=13.0 W=18.0 3-span	234	12/11/2020	3 Tons	MP	1989/1930
Webster	121/103	CLOTHESPIN BR ROAD	BLACKWATER RIVER	502-18	Deck 3 Serious Superstructure 5 Fair Substructure 4 Poor	L=73.0 W=20.6 1-span	1,504	12/11/2020	E-2	IB-C	1954
Westmoreland	089/100	RIVER ROAD SOUTH	PARTRIDGE BROOK	1,176-18	Deck 4 Poor Superstructure 4 Poor Substructure 4 Poor	L=147.3 W=25.3 6-span	3,727	11/19/2020	E-2	CTC	1937
Wilton	060/118	OLD COUNTY FARM RD	BLOOD BROOK	88-18	Deck 8 Very Good Superstructure 8 Very Good Substructure 3 Serious	L=26.0 W=18.0 1-span	468	11/13/2020	NPR	CS	2013/1950
Wilton	063/105	TEMPLE ROAD	BLOOD BROOK	1,176-18	Deck 3 Serious Superstructure 3 Serious Substructure 4 Poor	L=49.0 W=23.0 2-span	1,127	11/13/2020	10 Tons	MA	1901
Wilton	074/060	KING BROOK ROAD	KING BROOK	88-18	Culvert 3 Serious	L=12.0 W=20.0 1-span	240	11/13/2020	E-2	MA	1901
Wilton	080/145	FRYE MILL ROAD	BURTON POND OUTLET	41-18	Deck 8 Very Good Superstructure 8 Very Good Substructure 4 Poor	L=28.0 W=16.0 1-span	448	11/12/2020	NPR	CS	2014/1920
Winchester	063/101	RECYCLE WAY	ASHUELOT RIVER	45-19	Deck 6 Satisfactory Superstructure 7 Good Substructure 4 Poor	L=132.0 W=17.5 2-span	2,310	5/27/2020	E-2	IB-C	1985/1947
Windham	057/051	CASTLE HILL ROAD	BEAVER BROOK	287-19	Culvert 1 Closed - Failing	L=14.5 W=23.0 1-span	334	7/16/2020	BRC	MP	1984
Windham	099/044	MOECKEL ROAD	ROCK POND	134-19	Deck 4 Poor Superstructure 5 Fair Substructure 6 Satisfactory	L=18.0 W=18.0 1-span	324	7/16/2020	E-2	Jack	1940